

801 228<sup>th</sup> Avenue SE = Sammamish, WA 98075 = phone: 425-295-0500 = fax: 425-295-0600 = web: www.sammamish.us

## East Sammamish Park Baseball Field Improvements: Questions & Answers

## August 7, 2023

QUESTION	ANSWER
Does the Consultant need to include a geotechnical engineer on the project team or provide a geotechnical report as part of the project?	The Consultant is not required to include a geotechnical engineer on the project team. The City has a contract for geotechnical services that may be utilized to obtain a geotechnical report for this project.
Will the backstops at both baseball fields be replaced?	Yes, it is anticipated that backstops at both fields will be replaced.
What ADA improvements will be included as part of this project?	The City's 2021 ADA Transition Plan has identified key elements to be addressed as part of this project; these include but are not limited to dugout cross slopes, pavement slopes, accessible seating adjacent to bleachers, and accessible parking stall travel aisle striping.
Do the fields currently have underdrainage?	Yes, as-built documents identify field underdrainage.
Are there currently drainage issues in the grass outfields?	Yes, the outermost edges of the outfields have drainage issues and pool after rain events.
Will scoreboards be installed as part of this project?	No, scoreboards will not be installed. That said, the City may be interested in installing electrical conduit for future scoreboards. Power is available on-site already and terminates at both field backstops.